CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	1596-01
Description	SCRIPSIT
Model	Model 4
Stock No.	26-1596 Version 01.00.00
Date	April 14, 1984
Page 1 of	1

Problem

The following PATCHES correct misspelling of error messages and a problem with spooling.

* *   THE FOLLOWING PATCHES ARE REQUIRED!   * *

Solution

At TRSDOS READY, apply the following PATCHES to a BACKUP copy of SCRIPSIT.

PATCH SCRIPSIT/CMD (D25,14=45:F25,14=47:D25,1E=41:F25,1E=43)
PATCH SCRIPSIT/CMD (D0E,29=CDEB6100:F0E,29=4F3E06EF)
PATCH SCRIPSIT/CMD (D26,E2=4FF53E06EFF1C9:F26,E2=000000000000000)
PATCH SCRIPSIT/CMD (D00,4E=000000000000:F00,4E=2134383E67EF)
PATCH SCRIPSIT/CMD (D06,A9=31:F06,A9=30)

After the PATCHES from this bulletin have been applied, the Version number will be 01.00.01. Please make the necessary entry in your Version Log.