

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	<u>1588-01</u>
Description	<u>VIDEOTEX PLUS</u>
Model	<u>Model I/III</u>
Stock No.	<u>26-1588 Version 01.00.00</u>
Date	<u>April 17, 1984</u>
Page 1 of	<u>1</u>

Problem

Some of the UART settings in this package default to hex "6D". Apply the patch below to achieve a default setting of "6C" for 8, NONE and ONE.

* * THE FOLLOWING PATCH IS OPTIONAL! * *

Solution

At TRSDOS READY, apply the following PATCH to a BACKUP copy of VIDEOTEX PLUS.

PATCH VIDTEX/CMD (ADD=8441,FIND=6D,CHG=6C)

If this optional patch is applied, please make a notation of it on your Version Log. The Version number remains 01.00.00 after the application of the patch.