CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

400 Atrium-One Tandy Center, Fort Worth, Texas 76102

Problem

This program requires modifications as described below before it can be FCOPYED for hard disk use.

* * * These patches are required. * * *

Solution

At TRSDOS READY, apply the following patches to correct the above problem.

PATCH RSBASIC/LIO A=377D F=FD56Ø9FD5EØ8 C=Ø147ØØ9ØØØ
PATCH RSBASIC/LIO A=3786 F=ED53 C=ØØ22