

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4715-03
Description	BISYNC
Model	Model II
Stock No.	26-4715 Version 3.1
Date	March 26, 1982
Page 1 of	1

Problem

The BiSync package will lock up during Log On when interfacing with TSO running with TCAM. The following patch is to be used with version 3.1 of the BiSync package to correct the problem.

Solution

At TRSDOS READY, apply the following patch to correct the problem stated above.

PATCH BIS3270 A=7203 B=FE27 C=FE26