CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	3526-Ø1
Description	ENG. MATH II
Model	PC-2
Stock No.	26-3526 Version Ø1.ØØ.ØØ
Date	April 17, 1984
Page 1 of	1

Problem

Program VECTOR errs in rectangular polar conversion.

$*$ $*$ THE FOLLOWING CHANGE IS <u>REQUIRED</u>! $*$ $*$

Solution

1. In BASIC load the program by typing CLOAD"VECTOR".
2. Make the following corrections.

Old Line: 62Ø:Q=1:G=A:H=B:I=C:N=X:O=Y:P=Z:GOSUB 4Ø:A=X:B=Y:C=Z:M=-M+1:GOSUB 6Ø:M=R

New Line: 62Ø:Q=1:G=A:H=B:I=C:N=X:O=Y:P=Z:GOSUB 4Ø:IF MLET A=X:B=Y:C=Z

Add New Line: 627:M=-M+1:GOSUB 6Ø:M=R

3. Type CSAVE "VECTOR" to save the changes in the program to a new tape.
4. Make a backup of the corrected tape.

After the changes from this bulletin have been made, the Version number will be Ø1.ØØ.Ø1. Please make the necessary entry in your Version Log.