CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4150-11 (Correction 1)
Description	TRSDOS HD
Model	Model II/16
Stock No.	26-4150 Ver. 04.01.00
Date	January 17, 1983
Page 1 of	1

Problem

ERROR 48 (incorrect command parameter) occurs on returning from BASIC and immediately executing a save command which uses the indirect option.

* * The following patch is REQUIRED! * *

Solution

Customer Service Bulletin 4150-11 of November 12, 1982 was incorrect. It should read as follows:

PATCH SAVE R=6 B=141 F=18 C=07