CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	47Ø5-Ø6
Description	COMPILER BASIC
Model	Model II
Stock No.	26-47Ø5 Version 2.4
Date	Sept. 13, 1982
Page 1 of	1

Problem

BEDIT does not properly store source files when running under Model II TRSDOS 4.1. The result is garbled source.

* *   NOTE * *
The following patch is <u>required</u> for running under TRSDOS 4.1!
The following patch is <u>optional</u> for TRSDOS 2.Ø or 4.Ø!
The following patch should <u>NOT</u> be applied on TRSDOS 1.2!

Solution

At TRSDOS READY, apply the following patch to correct the above problem.

PATCH BEDIT {A=4184 F=3E3ØCF C=ØØØØØØ}