CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4912-Ø3
Description	TRSDOS II
Model	Model II/12 16
Stock No.	26-4912 Ver.Ø4.Ø2.Ø1
Date	May 18, 1983
Page 1 of	1

Problem

The Spool was turned on and the spool file created. The command to print Directory, DIR {PRT}, to the spool file was given. Some processing was done before an ERROR 45 (Printer Not Available) occurred.

* *   THE FOLLOWING PATCHES ARE REQUIRED!   * *

Solution

After patches from this Bulletin have been applied, the version number will be Ø4.Ø2.Ø2. Please make the necessary entry in your Version Log.

```
PATCH SYSTEM/SYS R=156 B=1Ø2 F=28 C=64
PATCH SYSTEM/SYS R=156 B=129 F=28 C=64
```