CUSTOMER SERVICE BULLETIN

Radio Shack®
CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	64Ø1-Ø1
Description	XENIX Development Sys.
Model	Model 12
Stock No.	26-64Ø1 Version Ø1.Ø2.ØØ
Date	October 25, 1983
Page 1 of	1

Problem

A file required by the procedure /etc/mkbf, was left off of the development system diskette. This gives a "Floppy Drive 3 NOT READY" error.

* *   THE FOLLOWING CHANGES ARE REQUIRED!   * *

Solution

These changes will correct the problem.

a)   Place the Core System (7ØØ-2Ø52) boot floppy in drive Ø and enter,

```
/etc/mount /dev/fdØ /mnt
cp /mnt/hdinit /etc
/etc/umount /dev/fdØ
```

b)   Remove the diskette and proceed normally.