

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4503-7
Description	Payroll
Model	Model II
Stock No.	26-4503 Version 1.0
Date	September 6, 1980
Page 1 of	1

Problem

The Model II Payroll program only allows state ID numbers to be 13 characters. It has been reported that the state of Missouri requires 17 characters. To allow 17 characters, change line 1090 in the 'CHNGCO' program. Only make this change if more than 13 characters are needed because a state ID this long will not fit properly on the W-2 forms.

Solution

The change can be made by following the steps listed below.

1. Backup the diskette(s) and make the changes on the Backup copy of the program.
2. In BASIC load the program by typing LOAD"CHNGCO".
3. Make the following corrections:

CHANGES (Retype the line or refer to the Edit section of the owners manual)

Old Line: 1090.....FL=30 ELSE FL=13

New Line: 1090.....FL=30 ELSE IF I=5 THEN FL=17 ELSE FL=13

4. Type SAVE"CHNGCO" to save the changes in the program.
5. At TRSDOS Ready, make a backup copy of the corrected diskette.