CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

Bulletin No. 4701-01

Description FORTRAN

Model Model II

Stock No. 26-4701 Version 1.0

Date May 21, 1982

Page 1 of _

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Problem

This program requires modifications as described below before it can be FCOPYED for hard disk use.

These patches are required for use on hard disk.

Solution

At TRSDOS READY, apply the following patches to correct the above problem.

PATCH EDIT A=5D53 F=CA635D C=ØØØØØØ PATCH EDIT A=5EDA F=6Ø C=61