

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	4705-06
Description	COMPILER BASIC
Model	Model II
Stock No.	26-4705 Version 2.4
Date	Sept. 13, 1982
Page 1 of	1

Problem

BEDIT does not properly store source files when running under Model II TRSDOS 4.1. The result is garbled source.

* * NOTE * *

The following patch is required for running under TRSDOS 4.1!

The following patch is optional for TRSDOS 2.0 or 4.0!

The following patch should NOT be applied on TRSDOS 1.2!

Solution

At TRSDOS READY, apply the following patch to correct the above problem.

```
PATCH BEDIT {A=4184 F=3E30CF C=000000}
```