

CUSTOMER SERVICE BULLETIN

Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

Bulletin No.	491Ø-25
Description	TRSDOS
Model	Model II
Stock No.	26-491Ø Version 1.2
Date	Feb. 23, 1982
Page 1 of	1

Problem

The following patches will correct LPRINT CHR\$(138) statements so that they cause a space character, carriage return to be issued to the printer. This is compatible with LPIII mode.

Solution

These patches are valid for QUME Printers on TRSDOS 1.2 only. After the patches are successfully applied, you must re-boot to use the printer. The patches are as follows:

```
PATCH IODVRS/SYS A=ØØ56 F=FFFFFFFFFFFFFFFFFFFFF  
C=213FØF3E8AB8CØØ62ØC9
```

```
PATCH IODVRS/SYS A=ØF47 F=213FØF C=CD56ØØ
```