

# CUSTOMER SERVICE BULLETIN

## Radio Shack® CUSTOMER SERVICE BULLETIN

400 Atrium—One Tandy Center, Fort Worth, Texas 76102

<b>Bulletin No.</b>	6105-01
<b>Description</b>	TRSDOS II
<b>Model</b>	Model II/16
<b>Stock No.</b>	26-6105 Version 4.1
<b>Date</b>	August 13, 1982
<b>Page 1 of</b>	1

### Problem

The TRSDOS II - 4.1 patches listed below should be used to alleviate a problem in the error recovery portion of BACKUP which, under certain circumstances, gives an ERROR 41.

\* \* THESE PATCHES ARE REQUIRED! \* \*

### Solution

At TRSDOS READY, apply the following patches to correct the above problem.

PATCH BACKUP {R=9 B=142 F=DE C=D8}

PATCH BACKUP {R=9 B=227 F=DE C=D8}