
## Errata: Installation Manuals for Sun Desktop Systems

This errata introduces two minor changes to the Sun desktop workstation chassis:

- The first change involves the way the monitor is attached to the chassis. Previously, the monitor rested in a dish-shaped cavity in the top of the chassis, where it was locked in place. The new desktop chassis is flat on top, with no cavity for the monitor. The base of the monitor is a flat pad, which simply rests on top of the chassis. Note that, because of this change, the monitor is now shipped separately from the chassis.
- □ The second change involves the positioning of the AC power receptacle for the monitor, and the voltage select, both located at the rear of the chassis. The positions of these two components, relative to each other, have been reversed. The AC power receptacle is now located above the voltage select, rather than below it (see the illustration below).



Part Number 800-2106-05 Revision: A of 16 August, 1988