

## ERRATA

**The Effects of Surface Treatments on Point Contact Transistor Characteristics** by J. H. Forster and L. E. Miller, B.S.T.J., **35**, pp. 767-811, July, 1956. Figs. 3, page 776, and 10, page 787, were inadvertently interchanged.

**Cable Design and Manufacture for the Transatlantic Submarine Cable System** by A. W. Lebert, H. B. Fisher and M. C. Biskeborn, B.S.T.J., **36**, pp. 189-216. Table I, page 3, the material for type B armor wire should be medium steel instead of mild steel. Page 207, the equation for  $Z_0$  should read

$$Z_0 = \frac{b}{\sqrt{\epsilon}} \log \frac{D}{b} \text{ ohms}$$