CUSTOMER SERVICE BULLETIN

Radio Shack CUSTOMER SERVICE BULLETIN

Builetin No. $^{\emptyset 312-13}$

Description TRSDOS

Model Model III

Stock No. $26-\emptyset 312 \text{ Ver. } \emptyset 1.\emptyset 3.\emptyset 1$

Date January 17, 1983

Page 1 of

400 Atrium-One Tandy Center, Fort Worth, Texas 76102

Problem

There is a typograpical error in HELP FORMS. "CR> = execute Top of Form" should appear on the screen instead of "CR> = execute Top or Form".

* * THE FOLLOWING PATCH IS REQUIRED! * *

Solution

After the patch from this Bulletin have been applied, the version number will be 01.03.02. Please make the necessary entry in your version log.

PATCH *8(ADD=5655,FIND=72,CHG=66)