

UPDATING SUPPLEMENT

9 NOV 1979

MANUAL IDENTIFICATION

Manual Serial No. Prefix: 1232, 1315, 1819

Manual Printed: JUNE 1978

Manual Part No.: 12539-90008

Microfiche Part No.:

SUPPLEMENT DESCRIPTION

The purpose of this supplement is to adapt the manual to equipment containing production improvements made subsequent to the printing of the manual and to correct manual errors. Enter the new information (or the Change Number, if more convenient) into the appropriate places in the manual, identified at left. For any given instrument serial number prefix, all change steps noted for prior serial number prefixes must be incorporated in addition to those for the given prefix.

	и	v		н.	u	IIV	76	· F	u	188	٠.	 4 4	N	v	(-	-	
							fi,										

Serial No. Prefix	Change
1945	1


ASSEMBLY CHANGES

Ref Des	Description	HP Part No.	Series	Changes
*				r,
· +				

Change 1 dated 9 November 1979.

US-1





1

DESCRIPTION

- . Title Page: Add "1945" to list of Serial Numbers covered.
- b. Pages 4-3/4-4: Revise R1 on schematics as follows:



Add the following footnotes to the schematics:

- *** Used only on PCA's with series no. 1819.
 - † Resistor removed on series no. 1945. If PCA is used in Select Code 17 of the computer mainframe, reinstall 150 ohm resistor in R1 slot located next to U24.

Revise R1 on Assembly drawing as follows:

R1* **

Add the following footnote to Assembly drawing:

† Resister removed on series no. 1945.

If PCA is used in Select Code 17 of the computer mainframe, reinstall 150 ohm resistor in R1 slot located next to U24.

- c. Page 5-2: On Assembly parts list, add "***" to "R1" and list the following footnote:
 - ****Used only on series no. 1819.
 R1 resistor deleted totally on series no. 1945